HELL TECHNIC CALL

Question

The left figure shows a steel half-disk with its center of mass E. The right figure shows the half-ring obtained by removing material from the half-disk, along with four additional points. Which point could be the location of the center of mass of the half-ring?

